



Notice of Hazard, Damage or Improvement

Overview	
Park Name	Grampians National Park - Gariwerd
Brief Description	<i>access track blockages and minor erosion</i>
General Location	<i>Mount Rosea</i>
Date Observed	<i>February 14 2023</i>
Reporter Details	Name: Phone: Email:
Report Date	28/02/23

Details - Issue #1	
Location	<i>Access track</i>
GPS Coordinates	<i>-37.179, 142.502</i>
Description	<i>Track is currently blocked by multiple fallen trees. Urgent action is required as the current situation could result in rescue delays in the event of an accident. The risk of falling over is high with the amount of debris on the track as well as impeding emergency responders if an accident occurs.</i>
Suggestions	<i>CSV recommends that Parks victoria should clear track of fallen trees asap. This could be followed up with volunteer working party with the guidance of PV staff, to install erosion control measures and clear remaining vegetation measures</i>
Photo	<i>Some example photos of the approximately 18 trees over the track</i>





